

**UNCLASSIFIED**

**AD 433496**

**DEFENSE DOCUMENTATION CENTER**

**FOR**

**SCIENTIFIC AND TECHNICAL INFORMATION**

**CAMERON STATION, ALEXANDRIA, VIRGINIA**



**UNCLASSIFIED**

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

64-11

433496

PRODUCTION ENGINEERING MEASURES  
TO INCREASE  
TRANSISTOR RELIABILITY  
FOURTH QUARTERLY PROGRESS REPORT

FOR THE PERIOD  
APRIL 1, 1963 THRU JUNE 30, 1963

CONTRACT NO. DA-36-039-SC-86730  
ITEM 4

PLACED BY  
U.S. ARMY ELECTRONICS MATERIEL AGENCY  
PHILADELPHIA, PENNSYLVANIA

433496

03-64-16

TEXAS INSTRUMENTS INCORPORATED  
SEMICONDUCTOR-COMPONENTS DIVISION  
DALLAS, TEXAS

PRODUCTION ENGINEERING MEASURES  
TO INCREASE  
TRANSISTOR RELIABILITY  
FOURTH QUARTERLY PROGRESS REPORT  
FOR THE PERIOD  
APRIL 1, 1963 THRU JUNE 30, 1963

OBJECT:

To evaluate and adopt proposed process improvements toward achieving a maximum failure rate of 0.01% per 1,000 hours at a 90% confidence level for the Silicon Triple Diffused Transistor Type 2N656.

CONTRACT NO. DA-36-039-SC-86730

ORDER NO. 19052-PP-62-81-81

CONTRACT ITEM 4, 2N656

  
Earl Gomersall - Power Department Manager

  
Elmer Wolff - Branch Manager of  
Power Department Engineering

  
Milton K. Mack - Power Department  
Section Head

  
James H. Overman - Power Department  
Group Leader

## TABLE OF CONTENTS

<u>TITLE</u>	<u>PAGE</u>
SECTION I      ABSTRACT	1
SECTION II     PURPOSE	2
SECTION III    NARRATIVE AND DATA	3
SECTION IV     CONCLUSIONS	20
SECTION V      PROGRAM FOR NEXT INTERVAL	21
SECTION VI     IDENTIFICATION OF PERSONNEL	22
SECTION VII    IDENTIFICATION OF TECHNICIANS AND MANHOURS WORKED	25

## SECTION I

### ABSTRACT

The process improvement work on the 2N656 device has been completed. Thermal resistance measurements indicate a power dissipation capability of 15 watts at 100°C case temperature. The Planar device improvements include "hard" gold alloy wafer mounting, ultrasonically cold-bonded contacts, and an improved "slug" package. Varnishes and organics have been completely eliminated from the inside of the package. Purity of the encapsulated atmosphere is assured by a thorough cleaning and baking of all parts and by rigid control of the assembly and canning dry-box atmosphere. The aluminum wafer contacts are never exposed to etchants. Corrosive chemicals have been eliminated from the assembly process. Improved processes in the diffusion, photo resist, etch, evaporation and plating areas have contributed to significantly increased product yields, quality and uniformity.

These process improvements have not only upgraded the 2N656, but also made possible the EIA reservation of a new device series, 2N2987 to 2N2994 — rated at 25 nanoamperes maximum  $I_{CEX}$  at 150% of rated  $BV_{CEO}$ . Saturation properties and current-carrying capabilities have been sufficiently improved such that  $V_{BE}$  and  $V_{CE(sat)}$  are specified at a collector current of 500 milliamperes as compared to the 200 milliampere rating of the Mesa 2N656.

## SECTION II

### PURPOSE

The purpose of the work provided in this contract is to:

1. Evaluate and adopt improved production processes.
2. Determine the degree of improvement in the operating failure rate resulting from the process improvements.
3. Supply the specified number of engineering test samples and reports to confirm the progress toward or attainment of the contract objective.

### SECTION III

#### NARRATIVE AND DATA

1. This section covers the engineering progress made during the fourth quarterly period of the contract. The engineering work items shown in the program plan, Table 1, have been completed.

Results of tests conducted in the first production planar devices were so impressive that all process improvement work performed during the fourth quarter was concentrated on the planar device. Work was discontinued on the mesa processes because it was felt that work in that area would detract from the process optimization effort on the planar device which has potential of much greater reliability. It should be noted that all 2N656 mesa devices produced since the start of this contract have benefited greatly from the process improvement work on this device series. The mesa has enjoyed the benefits of: improved photo-resist and diffusion processes; oxide-protected emitter-base junctions; improved processes for preparing collector side of the wafer; improved control over slug and crimp location; and improved electrical parameter data handling for process control. All tests that have been conducted on the mesa 2N656 series show that the quality and reliability have improved significantly since the start of the contract. However, it is felt that the mesa device will be rapidly replaced by the planar in all higher reliability applications as soon as availability of the planar is announced and reliability data distributed. The following narrative details the progress made on each of the items in the order they appear in Table 1.

##### 1.01 Uniform Penetration in Diffusion

Dale Bennett, Edmond McGhee

The improved diffusion and photo-resist facilities continue to produce high quality material at steadily increasing yields.

Planar diffusion processes have stabilized at reasonable production levels. Tests are in process to further improve yields by determining the optimum base penetration to get as far as practical below the mechanically disturbed silicon surface without sacrificing any of the electrical characteristics. The results of this work will come too late for any deeper base devices to be included in the reliability tests that will be conducted during the fifth and sixth quarters. However, experience has shown that the depth of the base has little, if any, effect on device reliability; but it may have a significant effect on yields and therefore affect costs. The improved cost situation will enhance the mass production capabilities of the planar device at prices competitive with the mesa, thus the decision was made to continue this engineering effort into the fifth quarterly period.

The economics of the automatic pre-diffusion slice cleaner mentioned in previous quarters have been re-evaluated and considered impractical at our present production levels. Consequently, it has been decided to continue with our present manual techniques and await production build-up before purchasing automatic or semi-automatic equipment

**PROGRAM PLAN**

STUDY	1962												1963												1964											
	J	A	S	O	N	D	J	F	M	A	M	J	J	A	S	O	N	D	J	F	M	A	M	J												
1. Uniform penetration in diffusion.																																				
2. Inert protective coatings for surface stabilization.																																				
3. Higher temperature alloys.																																				
4. Collector attachment.																																				
5. Thermal dissipation of package.																																				
6. Elimination of need for thermal compression bonding.																																				
7. Lead attachments.																																				
8. Surface passivation.																																				
9. Protective coating techniques for surface passivation.																																				
10. Welding, leak determination for encapsulation and sealing.																																				
11. Final preparation prior to sealing.																																				
12. Post weld conditioning.																																				
13. Inspection techniques.																																				
14. Process control improvement.																																				
Perform step stress and life tests to establish degree of reliability improvement.																																				

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100  
101  
102  
103  
104  
105  
106  
107  
108  
109  
110  
111  
112  
113  
114  
115  
116  
117  
118  
119  
120  
121  
122  
123  
124  
125  
126  
127  
128  
129  
130  
131  
132  
133  
134  
135  
136  
137  
138  
139  
140  
141  
142  
143  
144  
145  
146  
147  
148  
149  
150  
151  
152  
153  
154  
155  
156  
157  
158  
159  
160  
161  
162  
163  
164  
165  
166  
167  
168  
169  
170  
171  
172  
173  
174  
175  
176  
177  
178  
179  
180  
181  
182  
183  
184  
185  
186  
187  
188  
189  
190  
191  
192  
193  
194  
195  
196  
197  
198  
199  
200  
201  
202  
203  
204  
205  
206  
207  
208  
209  
210  
211  
212  
213  
214  
215  
216  
217  
218  
219  
220  
221  
222  
223  
224  
225  
226  
227  
228  
229  
230  
231  
232  
233  
234  
235  
236  
237  
238  
239  
240  
241  
242  
243  
244  
245  
246  
247  
248  
249  
250  
251  
252  
253  
254  
255  
256  
257  
258  
259  
260  
261  
262  
263  
264  
265  
266  
267  
268  
269  
270  
271  
272  
273  
274  
275  
276  
277  
278  
279  
280  
281  
282  
283  
284  
285  
286  
287  
288  
289  
290  
291  
292  
293  
294  
295  
296  
297  
298  
299  
300  
301  
302  
303  
304  
305  
306  
307  
308  
309  
310  
311  
312  
313  
314  
315  
316  
317  
318  
319  
320  
321  
322  
323  
324  
325  
326  
327  
328  
329  
330  
331  
332  
333  
334  
335  
336  
337  
338  
339  
340  
341  
342  
343  
344  
345  
346  
347  
348  
349  
350  
351  
352  
353  
354  
355  
356  
357  
358  
359  
360  
361  
362  
363  
364  
365  
366  
367  
368  
369  
370  
371  
372  
373  
374  
375  
376  
377  
378  
379  
380  
381  
382  
383  
384  
385  
386  
387  
388  
389  
390  
391  
392  
393  
394  
395  
396  
397  
398  
399  
400  
401  
402  
403  
404  
405  
406  
407  
408  
409  
410  
411  
412  
413  
414  
415  
416  
417  
418  
419  
420  
421  
422  
423  
424  
425  
426  
427  
428  
429  
430  
431  
432  
433  
434  
435  
436  
437  
438  
439  
440  
441  
442  
443  
444  
445  
446  
447  
448  
449  
450  
451  
452  
453  
454  
455  
456  
457  
458  
459  
460  
461  
462  
463  
464  
465  
466  
467  
468  
469  
470  
471  
472  
473  
474  
475  
476  
477  
478  
479  
480  
481  
482  
483  
484  
485  
486  
487  
488  
489  
490  
491  
492  
493  
494  
495  
496  
497  
498  
499  
500  
501  
502  
503  
504  
505  
506  
507  
508  
509  
510  
511  
512  
513  
514  
515  
516  
517  
518  
519  
520  
521  
522  
523  
524  
525  
526  
527  
528  
529  
530  
531  
532  
533  
534  
535  
536  
537  
538  
539  
540  
541  
542  
543  
544  
545  
546  
547  
548  
549  
550  
551  
552  
553  
554  
555  
556  
557  
558  
559  
560  
561  
562  
563  
564  
565  
566  
567  
568  
569  
570  
571  
572  
573  
574  
575  
576  
577  
578  
579  
580  
581  
582  
583  
584  
585  
586  
587  
588  
589  
590  
591  
592  
593  
594  
595  
596  
597  
598  
599  
600  
601  
602  
603  
604  
605  
606  
607  
608  
609  
610  
611  
612  
613  
614  
615  
616  
617  
618  
619  
620  
621  
622  
623  
624  
625  
626  
627  
628  
629  
630  
631  
632  
633  
634  
635  
636  
637  
638  
639  
640  
641  
642  
643  
644  
645  
646  
647  
648  
649  
650  
651  
652  
653  
654  
655  
656  
657  
658  
659  
660  
661  
662  
663  
664  
665  
666  
667  
668  
669  
670  
671  
672  
673  
674  
675  
676  
677  
678  
679  
680  
681  
682  
683  
684  
685  
686  
687  
688  
689  
690  
691  
692  
693  
694  
695  
696  
697  
698  
699  
700  
701  
702  
703  
704  
705  
706  
707  
708  
709  
710  
711  
712  
713  
714  
715  
716  
717  
718  
719  
720  
721  
722  
723  
724  
725  
726  
727  
728  
729  
730  
731  
732  
733  
734  
735  
736  
737  
738  
739  
740  
741  
742  
743  
744  
745  
746  
747  
748  
749  
750  
751  
752  
753  
754  
755  
756  
757  
758  
759  
760  
761  
762  
763  
764  
765  
766  
767  
768  
769  
770  
771  
772  
773  
774  
775  
776  
777  
778  
779  
780  
781  
782  
783  
784  
785  
786  
787  
788  
789  
790  
791  
792  
793  
794  
795  
796  
797  
798  
799  
800  
801  
802  
803  
804  
805  
806  
807  
808  
809  
810  
811  
812  
813  
814  
815  
816  
817  
818  
819  
820  
821  
822  
823  
824  
825  
826  
827  
828  
829  
830  
831  
832  
833  
834  
835  
836  
837  
838  
839  
840  
84

—

## 1.02 Inert Protective Coatings for Surface Stabilization

Edmond McGhee

The planar phase-in program shown in the third quarterly and on Table 1 was completed on schedule and formal production specifications were released early this quarter. Production devices were placed on environmental and life tests as follows:

TEST #	NO. DEVICES	DESCRIPTION OF TEST	PARAMETERS TO READ
1	67 (TO5)	200°C Storage for 1000 hours.	$I_{CES}$ , $BV_{CEO}$ , $I_B$
2	57 (TO5)	800 mw Operating at 25°C Ambient for 1000 hours.	$I_{CES}$ , $BV_{CEO}$ , $I_B$
3	36 (studded)	15 Watt Operating at 100°C Case for 1000 hours.	$I_{CES}$ , $I_{EBO}$ , $BV_{CEO}$ , $V_{BE}$ $h_{FE}$ , $V_{CES}$
4	37 (TO5)	1 Watt Operating at 25°C Ambient for 1000 hours.	Same as above
5	65 (TO5)	800 mw Operating at 25°C Ambient for 1000 hours.	$I_{CES}$ , $I_{EBO}$ , $V_{EBF}$ , $BV_{CEO}$ $h_{FE}$ , $V_{BE}$ , $V_{CES}$
6	65 (TO5)	200°C Storage for 1000 hours	(Same as above)
7	193 (TO5)	MIL-S-19500/263 (EL) Environmental Tests	(Same as above)

Tests 3 through 7 are incomplete; however, the incomplete data is quite good, indicating that our process improvement efforts have indeed yielded a high reliability device. Tests 1 and 2 have been finished with no failures per MIL-S-19500/74A criteria. The test results are shown on Tables 2 and 3. It should be noted that these devices were taken from the first lot of production devices, and some difficulty was being experienced with the purity of the final bake-out atmosphere (see 1.08 below). In spite of this, only 7 of the 124 devices started with  $I_{CES} > 2$  nanoamps and only 5 ended the test with  $I_{CES} > 2$  nanoamps. Both  $BV_{CEO}$  and  $h_{FE}$  were stable throughout the test.

This data and the incomplete data from the other tests have been evaluated and the decision has been made to register a new device. The key ratings and guaranteed parameters that will be on the new device data sheet are shown in Table 4. The most significant improvements in ratings and parameters on the new data sheet are: higher dissipation, lower leakages, higher current capabilities and lower saturation properties.

Data are being taken and compiled in order to show typical characteristics on a published data sheet. This sheet should be available next quarter.

# DATA SHEET (16-25)

TAKEN BY	DATE	PAGE OF
		1 3

TABLE 2

Planar 2N656 Life Test  
1000 hr. at 800 mw

UNIT #	ICES at $V_{CE} = 60$ V			$BV_{CEO}$ at $I_C = 30$ ma			$I_B$ at $V_{CE} = 5$ V, $I_C = 200$ ma			
	0 Hr NA	500 Hr NA	1000 Hr NA	0 Hr VOLTS	500 Hr VOLTS	1000 Hr VOLTS	0 Hr ma	500 Hr ma	1000 Hr ma	
68	< 1	< 1	1	97	95	94	2.68	2.87	2.88	
69	1	1	2	101	101	99	2.94	3.21	3.23	
70	< 1	< 1	1	91	89	88	2.63	2.72	2.69	
71	1	1	2	99	96	95	2.74	2.85	2.80	
72	1	1	2	102	100	98	3.14	3.22	3.17	
73	121	710	522	96	93	91	2.36	2.46	2.43	
74	1	< 1	1	91	90	89	2.19	2.30	2.27	
75	< 1	< 1	1	107	105	103	2.48	2.59	2.53	
76	< 1	< 1	2	110	107	105	3.66	3.86	3.80	
77	< 1	< 1	1	104	102	101	3.56	3.62	3.60	
78	8	< 1	1	92	91	91	3.32	3.53	3.43	
79	1	541	639	93	92	90	2.14	2.26	2.20	
80	< 1	< 1	2	106	102	101	2.78	2.86	2.80	
81	1	1	1	117	114	113	3.52	3.65	3.61	
82	1	< 1	1	98	96	94	3.93	4.10	4.05	
83	< 1	< 1	2	98	96	95	2.56	2.67	2.62	
84	1	1	1	100	97	96	2.86	2.92	2.82	
85	< 1	1	2	92	90	89	2.86	2.99	2.95	
86	1	< 1	2	102	100	98	2.80	2.90	2.85	
87	< 1	< 1	1	114	112	111	2.63	2.73	2.69	
88	2	1	1	87	86	85	2.22	2.33	2.30	
89	< 1	1	1	96	94	93	2.88	3.08	2.88	
90	1	< 1	2	118	113	113	2.92	3.01	2.97	
91	1	< 1	2	103	101	99	3.26	3.36	3.31	
92	6	< 1	2	93	91	90	3.38	3.50	3.45	

# DATA SHEET (16-25)

TAKEN BY	DATE	PAGE OF
		2   3

TABLE 2

UNIT #	I <sub>CES</sub> at V <sub>CE</sub> = 60 V				BV <sub>CEO</sub> at I <sub>C</sub> = 30 ma			I <sub>B</sub> at V <sub>CE</sub> = 5 V, I <sub>C</sub> = 200 ma				Planar 2N656 Life Test 1000 hr. at 800 mw		
	0 Hr NA	500 Hr NA	1000 Hr NA		0 Hr VOLTS	500 Hr VOLTS	1000 Hr VOLTS	0 Hr ma	500 Hr ma	1000 Hr ma				
93	< 1	< 1	1		88	87	86	2.48	2.58	2.56				
94	1	< 1	1		91	88	88	2.73	2.86	2.81				
95	1	< 1	2		118	116	115	3.23	3.32	3.29				
96	1	185	210		90	89	88	2.70	2.81	2.77				
97	1	1	1		94	94	93	3.01	3.34	3.18				
98	< 1	< 1	1		98	97	95	3.32	3.44	3.40				
99	5	1	1		105	103	102	2.59	2.69	2.61				
100	1	< 1	2		108	104	103	2.66	2.79	2.73				
101	1	< 1	1		99	96	95	3.40	3.51	3.45				
102	< 1	< 1	1		98	95	94	2.71	2.82	2.79				
103	< 1	< 1	2		99	98	96	4.01	4.15	4.09				
104	2	< 1	2		95	92	91	3.11	3.12	3.01				
105	< 1	1	1		99	96	95	3.62	3.74	3.69				
106	< 1	< 1	11		99	99	97	3.61	3.81	3.60				
107	1	< 1	1		99	99	99	2.63	3.00	3.12				
108	1	< 1	1		97	95	94	3.31	3.43	3.38				
109	< 1	< 1	1		96	94	93	2.96	3.04	2.98				
110	< 1	< 1	2		95	92	91	2.77	2.87	2.83				
111	< 1	< 1	1		96	96	94	3.29	3.39	3.28				
112	1	< 1	1		90	89	88	2.74	2.87	2.82				
113	1	< 1	1		98	95	96	3.20	3.35	3.29				
114	< 1	< 1	1		98	96	95	2.84	2.94	2.90				
115	< 1	< 1	1		96	94	93	2.42	2.51	2.46				
116	1	1	1		98	97	96	4.03	4.55	4.45				
117	< 1	< 1	1		93	90	89	2.22	2.30	2.25				

**Planar 2N656 Life Test  
1000 hr. at 800 mw**

[illegible]

DATA SHEET (16-25)

TAKEN BY	DATE	PAGE OF
		13

TABLE 3

UNIT #	ICES at $V_{CE} = 60$ V			$BV_{CEO}$ at $I_C = 30$ ma			$I_B$ at $V_{CE} = 5$ V, $I_C = 200$ ma			Planar 2N656 Life Test 1000 Hr. at 200°C		
	0 Hr NA	500 Hr NA	1000 Hr NA	0 Hr VOLTS	500 Hr VOLTS	1000 Hr VOLTS	0 Hr ma	500 Hr ma	1000 Hr ma			
1	< 1	< 1	2	96	94	93	4.00	3.80	3.90			
2	36	< 1	2	96	94	92	3.45	3.32	3.30			
3	< 1	< 1	2	109	106	105	3.59	3.55	3.47			
4	< 1	< 1	2	115	110	108	3.50	3.50	3.31			
5	1	< 1	2	102	98	97	2.52	2.51	3.52			
6	1	< 1	1	97	94	92	3.58	3.32	3.27			
7	1	< 1	2	87	85	84	2.27	2.32	2.38			
8	< 1	< 1	2	115	112	111	3.35	3.31	3.30			
9	< 1	< 1	1	98	95	93	4.07	4.01	4.01			
10	1	< 1	2	94	91	90	3.08	2.81	2.76			
11	1	< 1	2	89	86	85	2.46	2.52	2.50			
12	1	< 1	2	90	88	87	2.73	2.74	2.74			
13	1	< 1	2	94	92	91	2.70	2.73	2.70			
14	< 1	< 1	2	98	94	93	4.04	4.01	4.00			
15	1	< 1	2	91	89	88	2.86	2.89	2.87			
16	< 1	1	2	90	88	87	2.06	2.15	2.10			
17	< 1	< 1	2	114	109	108	2.87	2.85	2.83			
18	< 1	< 1	2	115	110	111	3.45	3.41	3.41			
19	1	1	2	90	88	87	2.70	2.78	2.75			
20	< 1	1	1	87	85	84	2.18	2.28	2.26			
21	< 1	< 1	1	104	100	100	3.39	3.38	3.37			
22	1	< 1	2	90	88	86	2.75	2.77	2.76			
23	< 1	1	2	92	89	88	2.96	2.96	2.88			
24	30	31	33	90	88	86	2.54	2.56	2.56			
25	1	1	2	98	94	93	2.52	2.55	2.54			

# DATA SHEET (16-25)

TAKEN BY	DATE	PAGE OF
		2 3

TABLE 3

Planar 2N656 Life Test 1000 Hr. at 200°C											
ICES at VCE = 60 V				BVCEO at IC = 30 ma				IB at VCE = 5 V, IC = 200 ma			
UNIT #	0 Hr NA	500 Hr NA	1000 Hr NA	0 Hr VOLTS	500 Hr VOLTS	1000 Hr VOLTS	0 Hr ma	500 Hr ma	1000 Hr ma		
26	< 1	1	2	113	109	108	3.20	3.17	3.15		
27	< 1	< 1	2	99	95	95	2.56	2.53	2.54		
28	1	< 1	2	89	85	86	2.35	2.38	2.39		
29	< 1	1	2	115	110	109	3.43	3.41	3.41		
30	1	< 1	2	106	101	99	2.66	2.65	2.59		
31	1	< 1	1	115	112	109	2.74	2.74	2.74		
32	< 1	< 1	2	98	95	95	2.57	2.58	2.58		
33	1	1	2	96	92	92	2.59	2.60	2.60		
34	1	< 1	1	98	95	94	4.09	4.09	3.87		
35	< 1	< 1	2	118	113	112	3.07	2.97	2.90		
36	21	1	2	98	93	93	3.45	3.11	3.03		
37	< 1	< 1	2	97	94	94	4.08	4.02	3.95		
38	< 1	< 1	11	92	89	88	2.90	2.97	2.89		
39	1	< 1	1	97	94	93	3.15	3.19	3.12		
40	< 1	1	1	106	102	100	3.30	3.20	3.23		
41	1	< 1	1	90	89	88	2.94	2.99	2.97		
42	1	< 1	1	98	93	93	3.42	3.13	3.08		
43	< 1	< 1	1	117	112	110	3.19	3.19	2.93		
44	< 1	< 1	1	89	87	88	2.30	2.37	2.29		
45	< 1	1	2	100	96	94	3.58	3.35	3.29		
46	1	1	2	99	94	93	3.92	3.68	3.58		
47	< 1	< 1	1	98	94	93	3.46	3.23	3.20		
48	< 1	< 1	2	103	97	97	3.69	3.42	3.37		
49	1	< 1	2	92	90	88	2.87	2.91	2.90		
50	1	< 1	2	106	101	101	3.09	3.09	3.02		

# DATA SHEET (16-25)

T1-2308

TAKEN BY	DATE	PAGE OF
		3 3

TABLE 3

Planar 2N656 Life Test  
1000 Hr. at 200°C

UNIT #	ICES at $V_{CE} = 60$ V			$BV_{CEO}$ at $I_C = 30$ ma			$I_B$ at $V_{CE} = 5$ V, $I_C = 200$ ma			
	0 Hr	500 Hr	1000 Hr	0 Hr	500 Hr	1000 Hr	0 Hr	500 Hr	1000 Hr	
	NA	NA	NA	VOLTS	VOLTS	VOLTS	ma	ma	ma	
51	< 1	1	2	112	108	107	3.31	3.28	3.11	
52	2	1	2	97	94	93	2.68	2.72	2.59	
53	< 1	< 1	1	100	95	95	3.66	3.39	3.29	
54	< 1	1	1	105	101	99	4.40	4.39	4.36	
55	1	1	2	103	99	98	3.18	3.20	3.11	
56	< 1	< 1	1	109	104	104	2.45	2.47	2.42	
57	1	< 1	1	90	87	86	2.48	2.60	2.52	
58	1	< 1	2	97	94	93	3.72	3.80	3.63	
59	1	1	1	98	94	93	3.35	3.34	3.22	
60	< 1	1	1	90	87	86	2.45	2.58	2.51	
61	< 1	1	2	104	100	101	2.59	2.63	2.58	
62	1	< 1	1	104	100	99	2.85	2.88	2.75	
63	1	1	1	93	91	89	3.03	3.11	2.86	
64	< 1	1	2	95	93	93	2.59	2.61	2.59	
65	< 1	< 1	2	90	86	86	3.23	3.12	3.00	
66	< 1	1	2	114	110	109	3.07	3.05	2.99	
67	1	< 1	2	94	91	89	2.55	2.60	2.56	

TABLE 4

A Summary of the Maximum Ratings and Guaranteed Parameters for the 2N2987 Series

	2N2987	2N2988
Absolute Max. Ratings at 25° Case Temp.	2N2989	2N2990
Collector-base Voltage	95 V	155 V
Collector-emitter Voltage	80 V	100 V
Emitter-base Voltage	7 V	7 V
Total Device Dissipation at 25°C Free Air Temp.	1 W	1 W
Total Device Dissipation at 100°C Case Temp.	15 W	15 W
Operating Case Temp. Range	-55 to +200°C	

## GUARANTEED PARAMETERS

PARAMETER	CONDITIONS	2N2987	2N2988	2N2989	2N2990	UNITS
$BV_{CEO}^*$	$I_C = 30 \text{ ma}$ , $I_B = 0$	80	Min	100	Min	V
$I_{CEO}$	$V_{CE} = 50 \text{ V}$ (2N2987) or (2N2989)	0.1	Max	0.1	Max	$\mu\text{a}$
	90 V (2N2988), $I_B = 0$ (2N2990)					
$I_{CEX}$	$V_{CE} = 90 \text{ V}$ (2N2987) or (2N2989)	0.025	Max	0.025	Max	$\mu\text{a}$
	150 V (2N2988), $V_{BE} = -1.5 \text{ V}$ (2N2990)					
$I_{CEX}$	Same as above at $T_C = 175^\circ\text{C}$	15	Max	15	Max	$\mu\text{a}$
$I_{EBO}$	$V_{EB} = 7 \text{ V}$ , $I_C = 0$	0.025	Max	0.025	Max	$\mu\text{a}$
$h_{FE}^*$	$V_{CE} = 5 \text{ V}$ , $I_C = 200 \text{ ma}$	25 to 75		60 to 120		—
$h_{FE}^*$	$V_{CE} = 5 \text{ V}$ , $I_C = 500 \text{ ma}$	20	Min	40	Min	—
$V_{BE}^*$	$V_{CE} = 5 \text{ V}$ , $I_C = 200 \text{ ma}$	0.9	Max	0.9	Max	V
$V_{BE}^*$	$I_B = 50 \text{ ma}$ , $I_C = 500 \text{ ma}$	1.4	Max	1.4	Max	V

TABLE 4 (Continued)

PARAMETER	CONDITIONS	2N2987	2N2988	2N2989	2N2990	UNITS
$V_{CE(SAT)}^*$	$I_B = 20 \text{ ma}, I_C = 200 \text{ ma}$	0.8 Max	0.8 Max	0.8 Max	0.8 Max	V
$V_{CE(SAT)}^*$	$I_B = 50 \text{ ma}, I_C = 500 \text{ ma}$	3.0 Max	3.0 Max	3.0 Max	3.0 Max	V
$h_{fe}$	$V_{CE} = 10 \text{ V}, I_C = 100 \text{ ma},$ $f = 1 \text{ kc}$	25 to 85	25 to 85	50 to 170	50 to 170	—
$ h_{fe} $	$V_{CE} = 10 \text{ V}, I_C = 100 \text{ ma},$ $f = 30 \text{ mc}$	1	1	1	1	—

\* Pulse Test

Some difficulty has been experienced with the scribing and breaking of the planar device, but it was traced to the optical system of the scribe and corrected. The system has been adequate for our mesa devices for there is adequate natural contrast between the mesa and the bottom of the "moat" where the scribing must be done. However, natural contrast is almost completely absent on the planar device; therefore, an improved lighting and optical system was essential before the operator was able to efficiently and accurately align the slices for scribing.

#### 1.03 Higher Temperature Alloys

Edmond McGhee

The "hard" gold eutectic alloy that was adopted for the planar device early in the process improvement program continues to give good results. (The "soft" solder used on the mesa device melts at 315°C and the "hard" gold eutectic melts at 356°C.)

#### 1.04 Collector Attachment

Edmond McGhee, Herbert D. Locke

The .010" thick molybdenum collector mounting substrate and the silver-copper eutectic braze continue to give excellent results. A specification was adopted which prohibits braze from creeping across the top of the "moly" any further than .010 in from the edge. This assures a uniform mounting surface for the collector side of the wafer.

The improved processes for preparing the collector side of the wafer are still yielding good results. Rigid control of the collector surface prior to and during the collector plating processes, and lot acceptance tests on the finished wafers are maintaining a high quality collector bond. The higher cost of the 200 microinch gold plate on the slugs, along with a slight problem with peripheral voids in the wafer mounting alloy, indicated a need to evaluate thinner gold plates. An evaluation determined that 50 microinch of gold yielded better peripheral void situation as well as lower costs.

#### 1.05 Thermal Dissipation of Package

John Kauffman

The improved dual tab package and the improvements in collector mounting, package staking, and crimping process have permitted us to increase the dissipation rating of the planar device. The device dissipation rating is now one (1) watt in 25°C ambient atmosphere and 15 watts with the case held at 100°C.

#### 1.06 Elimination of Need for Thermal Compression Bonding

Edmond McGhee  
Dale Bennett

Ultrasonic cold bonding and the improved high capacity processes for making the evaporated contacts continue to give good results. No difficulty has been experienced with opens or shorts in environmental tests to date. Complete data will be available next quarter.

#### 1.07 Lead Attachments

Edmond McGhee

The aluminum wafer lead welded to the gold plated Kovar header lead performs satisfac-

torily. The "fixed head" welder and microscope have virtually eliminated the "poor weld" problem that existed when hand held "tweezer" welders were used.

#### 1.08 Surface Passivation

Herbert Locke, Edmond McGhee

Initial experience with the planar processes indicated that the oxide must be extremely dry to be truly passive. Improved processes that were developed in our Semiconductor Research & Development Laboratories were evaluated and it was found that a 48-hour, high temperature, pre-can bake in a rapidly circulating, dry, inert atmosphere was adequate to achieve this passivation. The devices are then handled and canned in an inert atmosphere of no greater than 10 ppm moisture in order to maintain this passivation.

The importance of the purity in bakeout atmosphere was emphasized when a minute leak developed in an oven sufficient to slightly tarnish the parts in process. The tarnished devices were found to contain an appreciable quantity of electrically leaky devices. The oven leak was repaired and specifications were changed to prevent the recurrence of the situation.

#### 1.09 Protective Coating Techniques for Surface Passivation

Herbert Locke  
Edmond McGhee

A test was conducted to determine the effect of the best available silicone surface coating on the leakage level and/or stability of the planar device. Fifty-five (55) devices were surface treated and placed on 200°C storage and sixteen (16) devices on 800 mw operating test. Data are shown in Table 5. The test indicated excellent leakage stability at 200°C storage for the six weeks of the tests. However, the devices on 800 mw operating deteriorated rapidly with leakage of approximately half the devices increasing over four orders of magnitude in one week. The results of this test led us to conclude that the optimum protective coating for high reliability devices is clean, dry, silicon (planar) oxide.

#### 1.10 Welding, Leak Determination

James Overman

The quality of our final seal weld has improved significantly since the start of the contract. This has been a result of the excellent care and maintenance the welders receive from trained set-up men and the routine changeout and maintenance of the welder electrodes. The electrodes are changed after every 3000 welds and are dressed on an automatic refacing machine specifically designed to maintain the tight tolerances required for quality welds.

Attempts to determine the advisability of performing the helium leak test at a different point in the process were discontinued because of the availability of a radioactive tracer gas leak detecting process. The radioactive process is a standard leak test that costs more to perform than the helium leak test, but is considered by many to be more sensitive. Because of the cost, this test will not be adopted as the standard leak detection process for the production device. However, it will be available for those customers who request it and it will be used to check the devices that are going on test to confirm the degree of reliability improvement.

### 1.11 Final Preparation Prior to Sealing

Edmond McGhee

Improved processes in this area continue to give good results. All parts are rigorously cleaned, and hydrogen fired and sealed in dust-free plastic bags. The devices are removed from the bags in the dry box and are baked out in an inert atmosphere immediately prior to canning and are maintained in an inert atmosphere of  $< 10$  ppm moisture until after canning.

### 1.12 Post Weld Conditioning

Edmond McGhee

Processes developed by our Semiconductor Research and Development Laboratory personnel have indicated that no heat aging or burn-in of the planar devices is required. However, it was decided to use a 48-hour,  $200^{\circ}\text{C}$  heat-age as a precautionary measure.

### 1.13 Inspection Techniques

Herbert Locke

The process improvement whereby 100% of the wafers are electrically probed while still in slice form is giving excellent results. This technique permits us to salvage some of the increased planar material costs by reducing assembly and final test costs. These cost reductions are possible because the major portion of the defective wafers are now taken out prior to assembling — not at final test, after a slug, header, can and considerable labor have been expended.

It was determined that some of the good wafers were being damaged by the marker attachment to the probe. (The marker is used to identify defective wafers for post scribe and break culling.) The operator was having difficulty applying the correct amount of pressure to leave a visible mark without fracturing the slice. The problem was solved by designing a light, spring-loaded probe which would always apply the same pressure to the wafer during the defective wafer marking operation.

### 1.14 Process Control Improvement

Daily random samples are being pulled from the production line. Once each week the accumulated devices are run through a TACT (Transistor and Component Tester) machine and data are taken on the fifteen (15) different parameters and conditions shown in Table 6. This information is compiled and shown as distributions by our IBM 7074 computer. A weekly time plot of these parameter trends is maintained, showing the tenth, fiftieth and ninetieth percentile level for each parameter. This is an invaluable aid to the product engineer for detecting and correcting undesirable trends in the device.

**Life Test on Planar 2N656 Devices with High Purity Silicone Varnish Applied over Wafer.**  
Devices 9 thru 17 on 200°C Storage, Devices 65 thru 80 on 800 mw Operation

Devices 9 thru 17 on 200 °C Storage, Devices 65 thru 80 on 500 mW Operation									
DEVICE #	ICES at VCE = 90 V			hFE at VCE = 5 V, IC = 200 $\mu$ A	hFE at VCE = 5 V, IC = 200 $\mu$ A			200 $\mu$ A	
	INITIAL	1 Wk.	3 Wk.		6 Wk.	1 Wk.	3 Wk.		6 Wk.
9	.16 na	.16 na	.12 na	.14 a	31.2	26.4	22.7	22.7	
10	.12	.12	.11	.13	32.3	27.8	22.7	22.2	
11	.11	.11	.11	.12	26.3	25.0	21.3	20.8	
12	.16	.16	.14	.16	27.0	25.0	20.0	20.0	
13	.21	.21	.16	.19	23.2	23.2	19.6	19.6	
14	.22	.22	.19	.21	33.3	31.3	24.4	23.8	
15	.13	.13	.13	.13	25.1	22.2	19.2	19.0	
16	.19	.21	.18	.18	24.4	20.8	17.9	17.5	
17	.16	.16	.15	.16	25.0	23.8	20.0	20.0	
65	.14	.56 na	1.4 na	.97 na	23.6	20.8	22.1	25.3	
66	.17	.36 $\mu$ a	.59 $\mu$ a	15.3 na	23.8	19.8ky	100 Leaky	22.2	
67	.24	5.2 $\mu$ a	.39 $\mu$ a	.71 $\mu$ a	28.6	52.6	199ky	100ky	
68	.14	.11 $\mu$ a	.23 $\mu$ a	.54 $\mu$ a	32.3	45.5	58.9	32.8	
69	.17	1.5 na	.52 $\mu$ a	3.9 $\mu$ a	27.0	32.2	100 Leaky	100 Leaky	
70	.56	.35 na	.16 $\mu$ a	.41 $\mu$ a	25.6	25.4	100 Leaky	100 Leaky	
71	.68	1.1 na	.28 $\mu$ a	.220 $\mu$ a	27.0	26.3	100 Leaky	100 Leaky	
72	.12	.41 na	.24 $\mu$ a	.26 $\mu$ a	41.6	45.5	100 Leaky	100 Leaky	
73	.19	.750 $\mu$ a	.68 $\mu$ a	.48 $\mu$ a	38.5	100 Leaky	100 Leaky	100 Leaky	
74	.16	.450 $\mu$ a	.295 $\mu$ a	.33 na	27.8	100 Leaky	100 Leaky	100 Leaky	
75	.17	.860 na	.14 $\mu$ a	.26 $\mu$ a	24.4	32.2	43.5	100 Leaky	
76	.21	.62 na	.78 na	.34 $\mu$ a	25.6	27.0	37.0	100 Leaky	
77	.16	.8 na	.39 na	.40 na	30.3	26.2	14.9	16.4	
78	.14	.45 na	.42 na	.54 na	25.6	25.0	13.0	16.7	
79	.14	.21 $\mu$ a	.17 $\mu$ a	.66 $\mu$ a	25.0	100 Leaky	100 Leaky	100 Leaky	
80	.12	.27 na	3.6 na	.12 $\mu$ a	25.0	23.8	12.8	22.2	

TABLE 6

Test 2N2987 (Raw) Daily Production Samples on the TACT Machine for the Following Parameters, Conditions and Limits.

PARAMETER	CONDITIONS	FULL SCALE READING	MIN READING	CELL
$I_{EBO}$	$V_{EB} = 7 \text{ V}$	Automatic Range	0	.001
$I_{CEO}$	$V_{CE} = 50 \text{ V}$	Automatic Range	0	.001
$I_{CEO}$	$V_{CE} = 90 \text{ V}$	Automatic Range	0	.002
$I_{CEX}$	$V_{CE} = 90 \text{ V}, V_{CE} = -1.5$	Automatic Range	0	.002
$I_{CEX}$	$V_{CE} = 150 \text{ V}, V_{BE} = -1.5$	Automatic Range	0.0	.001
$BV_{EBO}$	$I_E = 10 \text{ microamp}$	100 V	6	.25
$h_{FE}$	$I_C = 1 \text{ ma}, V_{CE} = 5 \text{ V}$	1 ma	0	2.5
$h_{FE}^*$	$I_C = 200 \text{ ma}, V_{CE} = 5 \text{ V}$	100 ma	0	5
$h_{FE}^*$	$I_C = 500 \text{ ma}, V_{CE} = 5 \text{ V}$	100 ma	20	1.5
$V_{BE}^*$	$I_C = 200 \text{ ma}, V_{CE} = 5 \text{ V}$	10 V	0.5	.01
$V_{CE(SAT)}^*$	$I_C = 200 \text{ ma}, I_B = 20 \text{ ma}$	10 V	0	.01
$V_{BE(SAT)}^*$	$I_C = 200 \text{ ma}, I_B = 20 \text{ ma}$	10 V	0.6	.01
$V_{CE(SAT)}^*$	$I_C = 500 \text{ ma}, I_B = 50 \text{ ma}$	10 V	0.4	.03
$V_{BE(SAT)}^*$	$I_C = 500 \text{ ma}, I_B = 50 \text{ ma}$	10 V	0.7	.01
$BV_{CEO}^*$	$I_C = 30 \text{ ma}$	1000 V	50	2.5

\* Pulse Test

## SECTION IV

### CONCLUSIONS

The process improvement work on the 2N656 device has been completed. Significant process improvements and production capabilities have dictated registration of a separate device series with the EIA. During this report period, request for EIA reservation was made and temporary EIA numbers were received.

The following process changes have contributed most to the improvement of the device.

OLD PROCESS	NEW PROCESS
Mesa Wafer	Planar Wafer
Single .017 Dia. Slug Support	Double .012 x .075 Slug Support
Soft Solder	Hard Gold Alloy
Au to Al Thermocompression Bond	Al to Al Ultrasonic Bond
Inline (Post Mount) Etch	No Etchants Used in Assembly
Silicone Wafer Varnish	All Wafer Coating Eliminated

The Planar (2N2987 series) device is unilaterally interchangeable with the Mesa (2N656) device. Planar process improvements described in this report have been adopted as the standard parent production process from which both the 2N2987 series and the 2N656 can be supplied. To insure optimum utilization of the advantages gained through these process improvements, serious consideration should be given to specifying the planar process.

## SECTION V

### PROGRAM FOR NEXT INTERVAL

All preliminary environmental and life tests started on early production devices will be completed and analyzed. Planar 2N656 production devices will be screened from the 2N2987 series parent material and placed on test to confirm the degree of reliability improvement.

## SECTION VI

## IDENTIFICATION OF PERSONNEL

## HERBERT D. LOCKE

1961 - Present	Device Engineer, Silicon Power Transistors, TI
1959 - 1961	Engineering Technician, Silicon Power Transistors, TI
1958 - 1959	Assistant Supervisor, Silicon Power Transistors, TI

**MILTON K. MACK**

1956 - Present      Cost Center Supervisor, Silicon Power Transistor, TI

1949 - 1956      Manager, Compounding Laboratory, Dr. Pepper Company

1945 - 1949      Analytical Chemist, National Aniline Company

Author of "Polarographic Water Analysis" Control Engineering, October 1954

Holder of Patents No. 2,956,913 - Transistor and Method of Making Same  
No. 2,970,896 - Method for Making Semiconductor Devices

## EDMOND W. MC GHEE

B.S. in Physics, Baylor University, 1959  
B.Mus. in Theory and Composition, Baylor University, 1949  
M.Mus. in Music Literature, Baylor University, 1951

1959 - Present      Product Engineer, Silicon Power Transistor, TI

## CLARENCE H. MUNCIE

**B.S. in Electrical Engineering, Southern Methodist University, 1962**

<b>1962 - Present</b>	<b>Product Engineer, Silicon Power Transistors, TI</b>
<b>1959 - 1962</b>	<b>Co-Op Engineer, TI</b>
<b>1958 - 1959</b>	<b>Co-Op Engineer, GE</b>

**B. DEAN SCALLORN**

**B.S. in Chemical Engineering, University of Texas, 1956**

<b>1959 - Present</b>	<b>Quality and Reliability Assurance Engineer, Semiconductor Division, TI</b>
<b>1958 - 1959</b>	<b>Development Engineer of Vinyl Plastisols, The Barrier Corporation</b>
<b>1956 - 1958</b>	<b>Process Engineer on Manufacturing of Sulphuric Acid, Stauffer Chemical Company</b>

**JOHN E. KAUFFMAN**

<b>1963 - Present</b>	<b>Product (Mechanical Design) Engineer, Silicon Power Transistors, TI</b>
<b>1960 - 1963</b>	<b>Engineering Technician, Silicon Power Transistors, TI</b>
<b>1959 - 1960</b>	<b>Engineering Technician, Silicon Material Manufacturing, TI</b>

## SECTION VII

### IDENTIFICATION OF TECHNICIANS AND MANHOURS WORKED

<u>POWER DEPARTMENT PERSONNEL</u>	<u>HOURS WORKED</u>
<u>Salaried</u>	
Edward McGhee	406
Richard Stead	277.5
James Overman	296
Dale Bennet	246
Dean Scallorn	144
<u>Hourly</u>	
Harold Duncan	500
Dalma McBride	50 est.
John Kauffman	100 est.
Charles Ansley	50 est.
Quality Assurance Personnel	50 est.